

Update Prior to Sale UPS8013: Headlamp Aim

05-MAY-14 | No.: 6-229NAS | Section: GENERAL INFORMATION | Market: CAN / USA

DESCRIPTION

An issue has been identified on a limited number of 2014 model year Jaguar F-TYPE (X152) vehicles and 2013-2014 model year XK (X150) vehicles where the headlamp aim may have been incorrectly set.

AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

- F-TYPE (X152) K03708-K10050
- XK (X150) B50301-B54040

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin UPS8013-1bNAS: *Update Prior to Sale: Headlamp Aim*, for detailed repair instructions.

PARTS

No parts required

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY

NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'K211' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **16 June 2014** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No. / SUNDRY CODE	QTY. / VALUE
K211	B	Check headlamp aim	86.40.18	0.20	-	-
K211	C	Check headlamp aim	86.40.18	0.20	-	-
		Drive in/drive out	10.10.10	0.10	-	-

Normal Warranty policies and procedures apply