

Reference	SSM71822
Models	XK / X150 F-TYPE / X152 XJ / X351 XF / X250
Title	New vehicle storage (Transit relay / Transit mode)
Category	Electrical
Last modified	23-Apr-2014 00:00:00
Symptom	203000 Basic Electrical
Content	<p>Issue</p> <p>During a recent market visit it was noted that a significant number of dealers have been carrying out PDI's and then returning the vehicle to a storage compound without refitting the transit relay or returning the vehicle to transit mode.</p> <p>Transit mode / transit relay are designed to protect the customer's battery up to the point of delivery. All vehicles in storage MUST have the transit relay in place or be in transit mode.</p> <p>Action:</p> <p><u>Vehicles fitted with a transit relay</u></p> <p>If a new vehicle is returned to a storage compound following PDI the transit relay MUST be refitted to the vehicle. The device MUST remain on the vehicle until 72 hours prior to customer delivery.</p> <p><u>Vehicles equipped with transit mode.</u></p> <p>If a new vehicle is returned to a storage compound following a PDI it MUST be returned to transit mode. The vehicle must remain in transit mode until 72 hours prior to customer delivery.</p> <p>NOTE: If a vehicle is fitted with a Transit relay and has transit mode engaged you are not required to return the vehicle to transit mode but MUST have the transit relay is in place.</p>