

**UPDATE PRIOR TO SALE UPS5714: LUGGAGE
COMPARTMENT LID INTERIOR TRIM LOOSE**

**SERVICE
BULLETIN**

15-OCT-14

NO.: 6-248NAS
(issue 2)

SECTION: GENERAL
INFORMATION

MARKET: CAN / USA

CHANGES ARE HIGHLIGHTED IN GRAY

DESCRIPTION

A potential issue has been identified on a limited number of 2014 model year F-TYPE (X152; convertible only) vehicles where the luggage compartment lid interior trim may be loose / detached from the luggage compartment lid.

AFFECTED VEHICLES

The VIN range of affected vehicles is K09456-K10851.

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** only affected vehicles in the above VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action.

Refer to Technical Bulletin UPS5714-2bNAS, *Update Prior to Sale: Brake Booster Solenoid Connector Spring Locking Mechanism Not Engaged*, for detailed repair instructions.

PARTS

* when ordering parts, order the expected percentage demand of parts identified only

DESCRIPTION	PART No. / SUNDRY CODE	QTY. / VALUE*	EXPECTED % OF VEHICLES REQUIRING PART*
Trim - Luggage compartment lid - with retaining clips	T2R2008	1	50

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY

△ NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**K248**' together with the relevant Option Code

from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **02 April 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NO. / SUNDRY CODE	QTY. / VALUE
K248	B	Perform 3 luggage compartment lid 'slam shut' operations	10.10.99	0.20	-	-
K248	C	Perform 3 luggage compartment lid 'slam shut' operations	10.10.99	0.20	-	-
		Drive in/drive out	10.10.10	0.10	-	-
K248	D	Perform 3 luggage compartment lid 'slam shut' operations	10.10.99	0.20	-	-
		Replace luggage compartment lid trim	76.19.66	0.20	T2R2008	1
K248	E	Perform 3 luggage compartment lid 'slam shut' operations	10.10.99	0.20	-	-
		Replace luggage compartment lid trim	76.19.661	0.20	T2R2008	1
		Drive in/drive out	0.10.10	0.10	-	-

Normal Warranty policies and procedures apply