



UPDATE PRIOR TO SALE UPS7314-4b: SUPERCHARGER COOLING COOLANT PUMP DURABILITY CONCERN

SERVICE BULLETIN

31-OCT-14

NO.: 6-252NAS

SECTION: GENERAL INFORMATION

MARKET: CAN / USA

DESCRIPTION

A potential issue has been identified on a limited number of 2015 model year F-TYPE (X152) and XF (X250; 3.0L S/C V6 and 5.0L S/C V8 only) vehicles with the durability of the supercharger cooling coolant pump

AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

- F-TYPE (X152) K17935 - K18363
- XF (X250; 3.0L S/C V6 and 5.0L S/C V8 only) U51512 - U53535

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this Update Prior to Sale notice prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles within the listed VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin K261 UPS7314-4bNAS: *Supercharger Cooling Coolant Pump Durability Concern*, for detailed repair instructions.

PARTS

* when ordering parts, order the expected percentage demand of parts identified only

** an allowance equivalent approximately \$13.30 (£8.21) has been provided to cover the cost of the coolant

DESCRIPTION	PART NO. / SUNDRY CODE	QTY. / VALUE**	EXPECTED % OF VEHICLES REQUIRING PART*
Coolant pump	C2D37701	1	27
Coolant	ZZZ999	**\$13.30 (£8.21)	27

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY

△ NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'K261' together with the relevant Option Code. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the program's **03 April 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NO. / SUNDRY CODE	QTY. / VALUE
K261	B	Check the manufacturing label date on the coolant pump - no further action	05.10.20	0.20	-	-
K261	C	Check the manufacturing label date on the coolant pump - no further action Drive in/drive out	05.10.20 10.10.10	0.20 0.10	- -	- -
K261	D	Install a new supercharger cooling - coolant pump - F-TYPE	26.50.26	1.70	C2D37701 ZZZ999	1 ** £8.21
K261	E	Install a new supercharger cooling - coolant pump - F-TYPE Drive in/drive out	26.50.26 10.10.10	1.70 0.10	C2D37701 ZZZ999 -	1 **\$13.30 (£8.21) -
K261	F	Install a new supercharger cooling - coolant pump - XF	26.50.26	1.20	C2D37701 ZZZ999	1 **\$13.30 (£8.21)
K261	G	Install a new supercharger cooling - coolant pump - XF Drive in/drive out	26.50.26 10.10.10	1.20 0.10	C2D37701 ZZZ999 -	1 **\$13.30 (£8.21) -

**** an allowance equivalent approximately \$13.30 (£8.21) has been provided to cover the cost of the coolant**

Normal Warranty policies and procedures apply