1Front Headlamp Bumper Gap.pdf

Reference SSM53217

Models XF / X250

Title XF Bumper to Headlamp Gap

Category Body

Last modified 21-Feb-2014 00:00:00

Symptom 111000 Body Panel(s)/Unibody

Jaguar Cars have received reports on XF relating to poor gap / excessive profile issues between the front bumper and the front headlamps.

This is seen as a large gap between bumper and headlamp.

Cause:

Production standards inadequate.

Action:

Jaguar Cars have introduced an improved internal plant monitoring process to ensure the profile is improved. However on vehicles where the front bumper to headlamp Content gap profile is deemed unacceptable by the customer please adjust the front bumper to achieve the desired profile.

(see attached pdf. for fixing locations).

- 1. Locate 8mm bolt and loosen.
- 2. Apply pressure to the front of the bumper indicated by arrow 2 hold position and tighten bolt.

To centralise the front bumper cover follow these further steps to rectify.

- 1. Loosen 8mm bolts 1 to 4.
- 2. Move the bumper side to side to gain symmetry.
- 3. Tighten all 4 bolts.















