

Key cap fitting.pdf

Reference	SSM71538
Models	XK / X150 XJ / X351 XF / X250
Title	Door Lock Cylinder Cover - Fitment at PDI / Replacement.
Category	Body
Last modified	05-Feb-2014 00:00:00
Symptom	112000 Latches/Locks & Security
Content	Issue: Customer may report door lock cylinder cover missing. Cause: Cylinder cover may have been incorrectly fitted at PDI or after emergency vehicle entry. Action: The sequence of installing is shown on the attached doc. Please make sure that the door lock cylinder cover is pushed firmly in the sequence shown to install all 3 clips. The cover will now be securely attached to the vehicle. <u>Ensure correct fitment by testing with a vigorous pull</u>

