

Reference	SSM70478
Models	XJ / X351 XF / X250
Title	2.0 GTDI Turbocharger
Category	Engine
Last modified	02-Jan-2014 00:00:00
Symptom	403000 Exhaust System Concerns
Content	<p><u>Issue:</u> Customer complaint may identify a Turbocharger fault on 2.0 GTDI Engines from 12MY onwards, which includes re-manufactured units.</p> <p><u>Cause:</u> JLR are currently investigating the possible root causes with the Supplier, Borg Warner Turbo Systems.</p> <p><u>Action:</u> Please submit an ePQR and quote SSM 70478. JLR will then raise a Priority Parts request to send the Turbocharger unit to Borg Warner Turbo Systems for analysis.</p>