

SERVICE ADVISORY # 14-201

Kodiak Grill Bracket

Dutchmen Manufacturing, a division of Keystone RV Company, has determined that some Kodiak trailers have been manufactured with the wrong grill mounting bracket. This service advisory explains how to replace the mounting bracket.

Models Included: 2014 Dutchmen Kodiak Travel Trailers

Serial Number Ranges: 2014 EK176776 – EK176833

2014 EJ970000 – EJ970068

Parts Required: (1) KRV # 324311 Bracket - Bumper Mount Grill - Swing Arm - Lower Height

Tools Required: - Ratchet with 9/16" Deep Socket

REPAIR INSTRUCTIONS

ONE: REPAIR

Step 1 Flame King Grill Model # YSNHT-500 requires mounting bracket KRV# 324311. Remove the (2) U-bolts holding the bumper mount grill bracket to the bumper. Replace the bracket with KRV # 324311, secure with (2) U-bolts.

Step 2 Verify the grill mounting bracket bottom cross bar will rest against the bottom of the bumper mounted bracket. See figure 1 & 2.



Fig. 1

Grill bracket rests against the bottom of the bumper mount bracket

CORRECT
MONTING
BRACKET



Fig. 2

INCORRECT
MONTING
BRACKET

Grill bracket does not rest against the bottom of the bumper mount

TWO: WARRANTY REIMBURSEMENT

Submit the claim on Key Express using **Flat Rate Code # 7220142B** with **Service Advisory # 14-201** noted in the customer complaint section of the form. The amount of time authorized for this repair is 0.5 hours.

Please call Dutchmen RV Customer Service at **(866) 869-1110** if you have any questions.