



© 2014 Mazda Motor of America, Inc.

Subject: MIL ON WITH DTC P0780 AND/OR P1738 OR OTHER DTCS	Bulletin No: 05-003/14
	Last Issued: 12/22/2014

BULLETIN NOTE

- This bulletin has been replaced by service bulletin 05-005/14.
- This bulletin supersedes the previous bulletins 05-003/14 issued on 04/04/14 and 02/21/14 and 05-005/13 issued on 09/23/13, 9/25/13, 12/16/13, and 12/17/13.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.