

Door seal adrift.pdf

Reference	SSM71420
Models	LR2 / L359 Range Rover Evoque / L538
Title	Primary door seals coming adrift
Category	Body
Last modified	27-Jan-2014 00:00:00
Symptom	110000 Sealing
Content	<p>Issue: The primary door seals come adrift from the body at the bottom of the door aperture.</p> <p>Cause: The cause is being investigated and information is required to help establish root cause.</p> <p>Action: Please raise an EPQR detailing the measurements as shown in the attachment</p>

Door seal adrift

Please send two measurements of the door seal:

D - Distance of pull off

L - Length of loose seal (please straighten but don't stretch whilst measuring)

