


Valve Block Parts Breakdown (1).pdf

Reference	SSM71484
Models	Range Rover Sport / L320
Title	Dynamic Response Valve Block Lower Level Components Available
Category	Chassis
Last modified	03-Feb-2014 00:00:00
Symptom	304000 Suspension System
Content	<p><u>Issue:</u> A customer may complain that the dynamic response lamp is illuminated and diagnostic trouble codes (DTC) C 1119-09,C1119-22,C1119-62, C1119-91,C1B11-62, may be present.</p> <p><u>Cause:</u> Replacement of the valve block may not be required as lower level components are available. See attached document for component location and part numbers.</p> <p><u>Action:</u> Please refer to TOPIx Section 100-00 General Information, DTC: Dynamic Response Module (ARCM) for possible DTC causes and actions which have recently been amended.</p>



DMS  Unable to connect to the DMSi. Check the parameters and ensure that the DMSi is running.

Done