Reference	SSM71499
Models	Range Rover Evoque / L538
Title	14 MY Charge Light Illuminated (B1404-13 Flagged)
Category	Electrical
Last modified	31-Jan-2014 00:00:00
Symptom	206000 Warning Indicators
Content	Issue: Customer reports the charge light is illuminated within the cluster,  Cause: Potential software issue' Connect SDD and carry out a DTC read, B1404-13 is flagged  Action: Check Charge rate, (Doors Closed) Check all wiring, If OK procede to service function, extras, update Gateway module, clear DTC and test.