

Reference	SSM71638
Models	Range Rover / L322
Title	Start Stop switch splitting, deformed or crazed.
Category	Electrical
Last modified	16-Feb-2014 00:00:00
Symptom	203000 Basic Electrical
Content	<u>Issue</u> Customer reports that the start stop switch on the fascia is split, deformed or crazed.
	<u>Cause</u> Specification of material was not correct for application.
	<u>Action</u> A new switch is available, part number LR050802. Please order and fit this to rectify the customer concern.