

---

<b>Reference</b>	SSM72004
<b>Models</b>	Range Rover / L405
<b>Title</b>	L405 Front Door Fouls Wing / Fender post Vin LG192135
<b>Category</b>	Body
<b>Last modified</b>	25-Sep-2014 00:00:00
<b>Symptom</b>	111000 Body Panel(s)/Unibody
<b>Attachments</b>	

---

**Content****Concern**

A number of L405 Range Rover Dealers or Customers have reported that the Front Door Gille fouls the Wing / Fender upon the door opening.

**Action**

Land Rover Engineering have carried out a number of actions and are requesting that should you see this concern on a Vehicle past the vin Number **LG 192135**, that you please submit an EPQR with the following information:-

1. Photo of the foul condition
2. Measurement of the panel gapping between Door Gille & Fender / Wing in the door closed position
3. Confirmation that the Door is flush with the Wing / Fender, if not confirm which component is proud and give measurements
4. Confirmation that the Door Gille has not come adrift, if it has please confirm if it has come adrift due to a foul condition with the Wing / Fender or due to a fixing concern