

# NOTIFICATION OF UPDATE PRIOR TO SALE UPS7814-1B: DYNAMIC RESPONSE VALVE BLOCK SAFETY CONTROL VALVE STICKING OPEN

SERVICE BULLETIN

28-OCT-14 NO.: SGI14-45 SECTION: GENERAL MARKET: CAN / USA INFORMATION

## DESCRIPTION

A limited number of 2014-2015 model year Land Rover Range Rover Sport (L494) and Range Rover (L405) vehicles fitted with Dynamic Response may experience unexpected body movements when the vehicle is stationary due to the system self-test pulse resulting in pressure in the actuators which is normally isolated from them..

### AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

- Range Rover Sport (L494) ..... EA383752 FA394450
- Range Rover (L405) ...... EA180675 FA188790

#### **ACTION TO BE TAKEN**

Retailers are required to check DDW to ensure a vehicle is affected by Program Code 'Q427' and HOLD only affected new vehicles in your control and withhold them from onward distribution and sale pending further notice.

## SERVICE PROGRAM

Land Rover is currently in the process of developing a robust repair procedure. A further communication will be sent detailing the necessary action required for vehicles in retailer inventory.

Thank you for your cooperation in this matter. We apologize for any inconvenience this may cause.