Reference	SSM66837
Models	LR2 / L359
Title	Gearshift Interlock Button / Spring Issue
Category	Driveline
Last modified	31-Oct-2014 00:00:00
Symptom	503000 Automatic Transmission Engagement Concerns
Attachments	Appendix 1 Gear Selector.pdf Appendix 2 Gear Selector.pdf
Content	Issue:
	The gearshift interlock button inoperative or spring has come adrift (See Appendix 1)
	Cause:
	The interlock button mechanism has been modified to prevent this issue from Vin No. H372254 UK Build
	L910950 Pune Build
	Action:
	To resolve this issue please replace the gear selector knob ONLY
	(See Appendix 2)
	NOTE: Replacement of the complete assemby is NOT necessary.



