

<b>Reference</b>	SSM72017
<b>Models</b>	LR4 / L319 Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Range Rover, Range Rover Sport & Discovery 4 / LR4 Door Lower Cladding Loose
<b>Category</b>	Body
<b>Last modified</b>	02-Oct-2014 00:00:00
<b>Symptom</b>	108000 Ext. Trim/Accessories
<b>Attachments</b>	Door Cladding PoorFit.pdf (Door Cladding PoorFit.pdf)

**Content****Issue**

L405 Range Rover, L494 Range Rover Sport and Discovery 4 customers may report that the exterior lower door cladding is coming adrift/loose or a Gap is evident. The attached File shows examples.

**Cause**

Under investigation

**Action**

JLR are investigating this concern and in order for them to obtain more information should you see this concern you are requested to submit an EPQR with as much information as possible such as:-

1. At what mileage did the cladding become loose?.
2. Were all the locating clips fitted?
3. Were the locating clips distorted?
4. Is the vehicle washed by an Automatic Car wash?

Please supply photos of the Concern but also of the clips on the rear of the cladding once removed.

Your support is appreciated and will aid resolution of this concern.