
Reference	SSM72024
Models	Range Rover / L405 Range Rover Sport / L494
Title	Fault Diagnosis of Seating Lumbar/ Massage
Category	Body
Last modified	09-Oct-2014 00:00:00
Symptom	101000 Seating
Attachments	

Content

Issue: Diagnosis of seat lumbar/ massage concerns.

Cause: TOPIx diagnostic section previously not available.

Action: If a customer reports a concern with their seat lumbar/ massage functionality, please refer to the new TOPIx section below to aid diagnosis:

501-10 Seating - Diagnosis and Testing.