

Reference	SSM72072
Models	LR2 / L359 Range Rover Evoque / L538
Title	Alternator charging fault, 2.0 litre GTDi petrol derivatives only
Category	Electrical
Last modified	12-Nov-2014 00:00:00
Symptom	206000 Warning Indicators
Attachments	
Content	<p><u>Issue</u> Battery charging warning light is illuminated when driving or starting engine.</p> <p><u>Cause</u> Alternator regulator faulty in alternator part number LR028121.</p> <p><u>Action</u> A new regulator is now fitted to the alternator. The new alternator part number is LR067840. It replaces LR028121. Please ensure you order this part to rectify this customer issue.</p> <p>Assured vin for Evoque is FH995600 It was not fitted to Freelander 2 before the end of production therefore all vehicles affected.</p> <p><u>Ratings:</u> Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern. 3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern. 5 = Excellent – All required information provided to resolve the customer concern.</p>