



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

CSC-10057551-7625

March 2015

RE: 2013 Fit EV Plug-In

Dear Honda Fit EV Owner:

What is the reason for this notice?

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. The 2013 Fit EV is designed to charge at a high rate resulting in a shorter charge time. In rare cases, there may be a poor connection between the charger and the charge inlet that causes the inlet to overheat. To protect the charge inlet from damage, the vehicle stops charging, even if the vehicle is not fully charged. A software update has been developed that will allow the vehicle to finish charging at a slightly reduced rate in order to lower the inlet terminal temperature, but this may increase the charge time. The software update will also program the green LED, located at the charge connector, to blink rapidly when the vehicle is charging at a reduced rate.

What should you do?

Please contact any authorized Honda dealer to schedule a service appointment. The dealer will update your vehicle *free of charge*.

The dealer will also apply a self-adhesive update to the owner's manual, so please make sure it is in the vehicle when you have the software update done.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this product update may cause you. We are taking this action in the interest of your safety and continued satisfaction with your Honda vehicle.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #14-004

JD4

Marzo 2015

RE: 2013 Fit EV Plug-In

Estimado propietario de un vehículo Honda Fit EV:

¿Cuál es el motivo de esta notificación?

Nuestros registros indican que no se ha completado una ACTUALIZACIÓN DE PRODUCTO en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. El Fit EV 2013 está diseñado para cargarse a una alta tasa de carga con el resultado de un tiempo de carga más corto. En casos raros, puede haber una mala conexión entre el cargador y la admisión de la carga que ocasione que la admisión de la carga se sobrecaliente. Para proteger de daños la admisión de la carga, el vehículo deja de cargarse, inclusive si no está completamente cargado. Una actualización se ha desarrollado la cual permitirá que el vehículo termine de cargarse a una tasa de carga ligeramente reducida con el fin de disminuir la temperatura del terminal de admisión pero esto puede aumentar el tiempo de carga. La actualización del programa también programará el LED verde, ubicado en el conector de carga, para parpadear rápidamente cuando el vehículo está cargándose a una tasa reducida.

¿Qué debe hacer?

Por favor comuníquese con cualquier concesionario autorizado Honda para programar una cita de servicio. El concesionario actualizará su vehículo *sin costo alguno*.

El concesionario también aplicará una actualización auto-adhesiva al manual de propietario, así que asegúrese que se encuentre en el vehículo cuando se realice la actualización del programa.

Si tiene preguntas

Si tiene preguntas acerca de esta notificación o necesita asistencia para ubicar un concesionario, comuníquese con Atención al Cliente de Automóviles Honda al 1-888-234-2138. Usted también puede encontrar esta información en www.Hondacars.com.

Le pedimos disculpas por cualquier inconveniente que pueda haberle causado esta actualización de producto. Nosotros estamos tomando esta acción en el interés de su seguridad y satisfacción continua con su vehículo Honda.

Atentamente,

**American Honda Motor Co., Inc.
División Automotriz de Honda**

AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BOLETÍN DE SERVICIO #14-004
JD4