## **CSC-10058683-6181** June 2015

This notice applies to your vehicle, VIN: \_\_\_\_\_

Dear General Motors Customer:

As the owner of a 2013-2015 model year Chevrolet Trax or Buick Encore vehicle, your satisfaction with our product is very important to us.

On certain 2013-2015 model year Chevrolet Trax and Buick Encore vehicles, the rear-seat-belt buckle cover may be broken and fully separated from the rear-seat-belt buckle due to seat-belt-buckle head contact between the ISO fixture and the seat-hinge stud, seat-hinge bracket, or floor panel. This can occur if the buckle is not properly retained in the routing strip. Over time, the seat-belt buckle may intermittently not lock or the webbing may separate from the seat-belt buckle if the buckle cover becomes detached.

## Do not take your vehicle to your GM dealer as a result of this letter unless you believe that your vehicle has the condition as described above.

**What We Have Done:** General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your vehicle within 10 years of the date your vehicle was originally placed in service or 120,000 miles (193,000 km), whichever occurs first, the condition will be repaired for you at **no charge**. Diagnosis or repair for conditions other than the condition described above is not covered under this special coverage program.

What You Should Do: If you believe that your vehicle has the condition described above, repairs and adjustments qualifying under this special coverage must be performed by a General Motors dealer. You may want to contact your GM dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

**Reimbursement:** If you have paid for repairs for the condition described in this letter, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by June 30, 2016, unless state law specifies a longer reimbursement period.

If you have any questions or need any assistance, just contact your dealer or the appropriate Customer Assistance Center at the number listed below.

| Division              | Number         | Text Telephones<br>(TTY) |
|-----------------------|----------------|--------------------------|
| Buick                 | 1-800-521-7300 | 1-800-832-8425           |
| Chevrolet             | 1-800-222-1020 | 1-800-833-2438           |
| Guam                  | 65-6267-1752   |                          |
| Puerto Rico – English | 1-800-496-9992 |                          |
| Puerto Rico – Español | 1-800-496-9993 |                          |
| Virgin Islands        | 1-800-496-9994 |                          |

We are sorry for any inconvenience you may experience; however, we have taken this action in the interest of your continued satisfaction with our products.

Alicia S. Boler-Davis Sr. Vice President Global Connected Customer Experience

Enclosure 14567