



Tech Tips

TT 01-15-07

Date: November 6, 2015

2011-2014 2.5L Jetta, Passat, Golf – with P1386 Control
Module Faulty

November 13, 2015: Correction to fault code.

In the event of fault code **P1386** setting in the ECM, replace the G28 (engine crankshaft speed sensor).