



Tech Tips

TT 01-15-07

Date: November 6, 2015

**2011-2014 2.5L Jetta, Passat, Golf - with P1386 Control
Module Faulty**

In the event of fault code P1368 setting in the ECM, replace the G28 (engine crankshaft speed sensor).