## **CONDITION**

Customer may complain about a MIL "ON" condition with P0AFC.

## **RECOMMENDATIONS**

- 1. Check for aftermarket antenna in trunk area such as CB radio antenna.
- 2. If aftermarket antenna is found in trunk area it may cause DTC P0AFC to set, move antenna to a different location.
- 3. If DTC is present and there is no aftermarket antenna being used near the trunk area, then follow repair manual procedure for DTC P0AFC.

## **LINK REFERENCES**

4. <u>HYBRID / BATTERY CONTROL: HYBRID BATTERY SYSTEM: P0AFC-123; Hybrid Battery</u> Pack Sensor Module: 2015 MY Camry HV [09/2014 - ???????]

Expires on 09/08/2016