

View Message

Sent on	10	19	2015	Expires on	10	30	2015
From	Parts and Service Division						
Subject	Request for Parts: 2015 TLX Electronic Parking Brake (EPB) Actuator Inop						

PRIORITY/ACTIONREQUIRED

To: All AcuraService Managers/Consultants
From: TechnicalResearch & Support Group
RE: Requestfor Parts: 2015 TLX Electronic Parking Brake (EPB) Actuator Inop

This message is solely directed to Acura dealership personnel; please handle accordingly.

Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2015 TLXs with a client reporting on ignition start, the Electronic Parking Brake (EPB) will not release causing one or both rear wheels not to move and/or "Check Parking Brake" warning message displays in MID. To fully understand the cause of this occurrence, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

1. Troubleshooting leads technician to replace the EPB Actuator.
2. No previous repairs.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions. Thank you.