
Reference	SSM72140
Models	LR2 / L359 Range Rover Evoque / L538
Title	Air Conditioning Compressor Clutch Failure
Category	Electrical
Last modified	20-Jan-2015 00:00:00
Symptom	208000 Climate Control

Content**Issue:**

Engineering have received reports of compressor clutch failure on 2.0 Petrol, & 2.2 Diesel Freelander & Evoque models.

Cause:

Internal issue within clutch.

Action:

Clutch has been modified to resolve issue

Assured VIN No.

Freelander H383608 / Pune 911069

Evoque H846359

Thank you to everyone who submitted reports for compressor clutch failure, please only submit further EPQR's if you have issues with vehicles that are built after the above assured VIN numbers