

Reference	SSM66837
Models	LR2 / L359
Title	Gearshift Interlock Button / Spring Issue
Category	Driveline
Last modified	09-Feb-2015 00:00:00
Symptom	503000 Automatic Transmission Engagement Concerns
Attachments	1Appendix 1 Gear Selector.pdf 1Appendix 2 Gear Selector.pdf

Content**Issue:**

The gearshift interlock button inoperative or spring has come adrift (See Appendix 1)

Cause:

The interlock button mechanism has been modified to prevent this issue from Vin No. H372254 UK Build L910950 Pune Build

Action:

To resolve this issue please replace the gear selector knob ONLY
(See Appendix 2)

NOTE: Replacement of the complete assembly is **NOT** necessary.

Please only submit further EPQR's for any vehicles that were manufactured later than the above assured VIN's



