
Reference	SSM72175
Models	Discovery Sport / L550 Range Rover Evoque / L538
Title	P0936-64 DTC stored
Category	Driveline
Last modified	06-Feb-2015 00:00:00
Symptom	501000 Automatic Transmission Concerns

ContentIssue:

On a small number of L538 Evoque and L550 Discovery sport vehicles (14 and 15 model year), DTC P0936-64 may be stored in the TCM.

Cause:

Internal transmission diagnostics have been triggered.

Action:

L550 - Replace the transmission

L538 within VIN range EH792089-FH035650 - Check the status of service action Q450.

- If service action Q450 is outstanding – Complete service action and thoroughly test vehicle to validate repair. (If vehicle still exhibits the same symptom, replace the transmission).
- If service action Q450 closed – Replace the transmission.

L538 VIN FH035650 or later - Replace the transmission.