

<b>Reference</b>	SSM72189
<b>Models</b>	Range Rover / L405
<b>Title</b>	Rear Spoiler Contact With `D` Post
<b>Category</b>	Body
<b>Last modified</b>	23-Feb-2015 00:00:00
<b>Symptom</b>	111000 Body Panel(s)/Unibody
<b>Attachments</b>	Rear Spoiler Contact.jpg
<b>Content</b>	<p><b><u>Issue</u></b></p> <p>Rear spoiler contact with "D" post marking both trim panel and / or spoiler (see attached picture)</p> <p><b><u>Cause</u></b></p> <p>Incorrect setting at manufacture</p> <p><b><u>Action</u></b></p> <p>Tailgate setting process within manufacturing revised at VIN A216844</p> <p><b>JLR engineering would like to thank everyone who submitted EPQR's highlighting and assisting this investigation. Please only submit further EPQR's for vehicles manufactured after the assured VIN A216844</b></p>

