

<b>Reference</b>	SSM72199
<b>Models</b>	Range Rover / L405
<b>Title</b>	L405 15.5MY Powered Lower Tailgate Soft Close Cinch Operation
<b>Category</b>	Body
<b>Last modified</b>	27-Feb-2015 00:00:00
<b>Symptom</b>	112000 Latches/Locks & Security
<b>Content</b>	<p>Issue                      L405 15.5MY Range Rover Customers may report that the Lower Powered Tailgate Soft Close Cinch operation fails to close fully. Note:-                      The Tailgate can be closed manually</p> <p>Cause                      Incorrect software level in the Rear Tailgate Module</p> <p>Action                      JLR will release an update software patch for this concern shortly.                      In the meantime you are requested to not replace any parts as they will be at the same software level.</p>