

Reference	SSM72233
Models	LR4 / L319
Title	Tailgate switch harness corrosion. Pre 14my vehicles only
Category	Body
Last modified	27-Apr-2015 00:00:00
Symptom	112000 Latches/Locks & Security

ContentIssue

The tailgate will not open from the exterior tailgate switch.

Cause.

The wires to the switch have corroded and are possibly broken.

Action

A new switch is available with improved wire material.

If you have this failure you should fit the new part from this list.

<u>Description number</u>	<u>Original part number</u>	<u>New part</u>
Tailgate switch assembly, less camera LR071910	LR015457	
Tailgate switch assembly, fixed camera LR071911	LR015458	
Tailgate switch assembly, surround camera system LR071912	LR015459	

Microcat will be updated at the earliest opportunity.

Note: From 14my onwards all production vehicles are fitted with the improved wire material.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.