

| | |
|----------------------|--|
| Reference | SSM72272 |
| Models | LR3 / L319 (512947 → 474451) Range Rover Sport / L320 (215620 → 164843) |
| Title | 09MY Range Rover Sport or LR3 MIL illuminated & DTC P0430 or P0420 |
| Category | Engine |
| Last modified | 18-May-2015 00:00:00 |
| Symptom | 403000 Exhaust System Concerns |

Content

Issue:

09MY

Range Rover Sport 4.4 NA or LR3 4.4 NA

-Repair triggered due to MIL light caused by DTC P0430 or P0420.

-Mileage: less than 80,000 miles

-No previous incidence of misfire DTC P03xx

Cause:

Possible fault with exhaust catalytic converter.

Action:

Please replace both banks of the exhaust catalyst even though the diagnosis only indicates a single side to be replaced.

Retain the following parts for possible return to aid investigation:

WCD502470 (7H22 9N497 DB) (RH Cat)

WCD502480 (7H22 9N497 EB) (LH Cat)

Please submit an EPQR so collection of the parts can be arranged.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.