

TECHNICAL BULLETIN

LTB00319NAS4
16 JUN 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in gray

SECTION: 501-08

Exterior A-Pillar Molding Loose

AFFECTED VEHICLE RANGE:

LR3 (LA)

Model Year: 2005-2009

VIN: 5A000360-9A513325

LR4 (LA)

Model Year: 2010-2013

VIN: AA510742-DA680025

Range Rover Sport (LS)

Model Year: 2005-2013

VIN: 6A900290-DA778722

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The exterior A-pillar molding may become loose.

Cause: This may be caused by the molding's retaining clips losing tension.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

LR077843	A-Pillar Retaining Clips Fitting kit	Quantity: 1
----------	--------------------------------------	-------------

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIX to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Finisher - Windshield - Side - Left-hand - Renew	76.43.39	0.1	07	DYC500020
Finisher - Windshield - Side - Right-hand - Renew	76.43.40	0.1	07	DYC500020



NOTE: Normal Warranty procedures apply.

SERVICE INSTRUCTION:

1. Install the new A-pillar exterior finisher retaining clips (see TOPIx Workshop Manual, section 501-08).