

Reference	SSM72290
Models	Range Rover / L405 Range Rover Sport / L494
Title	L405 Range Rover & L494 Sport Squeaks & Creaks Diagnostic`s
Category	Body
Last modified	01-Jun-2015 00:00:00
Symptom	110000 Sealing

Content

Issue

L405 Range Rover and L494 Range Rover Sport Customers may report a 'Creak' or 'Squeak' from either of the Front or Rear Doors

Cause

Possible causes could be :-

- Obstruction within door aperture or door latch
- Incorrect door striker- Alignment/adjustment
- Door frame seal coating
- Worn/damaged door frame seal(s)
- Worn/damaged door aperture seal(s)
- Paint wear

Action

Pinpoint diagnostics within Topix have been newly created to help the Technician diagnose the correct route cause and resolution. These can be found in the Workshop Manual -*Body & Paint – 501-00 – Diagnosis & Testing –Squeaks and Rattles.*