



Reference	SSM72299
Models	Discovery Sport / L550
Title	L550 Discovery Sport Reverse Lamp Low Level Repair
Category	Electrical
Last modified	16-Jun-2015 00:00:00
Symptom	201000 Lighting Systems
Attachments	1bulb.pptx
Content	<p><u>Issue:</u> Replacement of the tailgate lamp assembly when the reverse bulb(s) does not illuminate.</p> <p><u>Cause:</u> Microcat low level repair not available as a separate part for L550 but is available for Freelander2 (L359) and Evoque (L538).</p> <p><u>Action:</u> Please order the lamp LR000699 (W16W reverse bulb), rather than ordering a new tailgate lamp assembly (listed below) for this issue.</p> <ul style="list-style-type: none">• LR060909 - Hi Line NAS LH• LR060897 - Hi Line NAS RH• LR060908 - Low Line NAS LH• LR060896 - Low Line NAS RH• LR060893 - Low Line ROW RH• LR060906 - Low Line ROW LH• LR060894 - Hi Line ROW RH• LR060907 - Hi Line ROW LH <p><i>(Hi Line Vehicles = Xenon Headlamp ,Low Line Vehicles = Halogen Headlamps)</i></p> <p>Note - Microcat will be updated for L550.</p>



Tailgate lamp
assembly.