

TECHNICAL BULLETIN

LTB00749NAS1
08 APR 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 303-04

Engine MIL Illuminated With DTC P008B Stored - Information Only

AFFECTED VEHICLE RANGE:

LR2 (LF)

Model Year: 2013-2014

VIN: DH311358-EH439912

Range Rover Evoque (LV)

Model Year: 2012 Onwards

VIN: CH600000 Onwards

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The engine Malfunction Indicator Lamp (MIL) may be illuminated and Diagnostic Trouble Code (DTC) P008B is stored in the Engine Control Module (ECM).

Cause: This may be caused by an internal fault with the low pressure fuel sensor.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

No Parts Required

TOOLS:

SDD with latest DVD and Calibration File
Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:

 **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

 **NOTE:** DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Information only	-	0	-	-

 **NOTE:** Normal Warranty procedures apply.

SERVICE INSTRUCTION: