
Reference	SSM72214
Models	Discovery Sport / L550
Title	Blind Spot Monitoring (BSM) inoperative
Category	Electrical
Last modified	08-Apr-2015 00:00:00
Symptom	206000 Warning Indicators
Content	<p><u>Issue</u> Blind Spot Monitoring inoperative with the following DTC's logged: U0010 - 87 Missing Message. U1A00 - 88 Private Network Off Bus.</p> <p><u>Cause</u> Side Object Detection Left/Right - SODL and SODR not configured.</p> <p><u>Action</u> Update SODL and SODR as existing modules to correct this issue.</p>