

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 72233 - Tailgate switch harness corrosion. Pre 14my vehicles only

Models : LA - Discovery 4 / LR4

Engineer Bucknall Simon

Name :

Last Modified 27-04-2015 09:47:42

:

Category : Body

Symptom : 112000 Latches/Locks & Security

Content : Issue

The tailgate will not open from the exterior tailgate switch.

Cause.

The wires to the switch have corroded and are possibly broken.

Action

A new switch is available with improved wire material. If you have this failure you should fit the new part from this list.

Description

Original part

number New part number

Tailgate switch assembly, less
camera LR015457
LR071910

Tailgate switch assembly, fixed
camera LR015458
LR071911

Tailgate switch assembly, surround camera system
LR015459 LR071912

Microcat will be updated at the earliest opportunity.

Note: From 14my onwards all production vehicles are fitted with the improved wire material.

