

Reference	SSM72241
Models	Range Rover / L405 Range Rover Evoque / L538
Title	Exterior door handle keyless sensor inop
Category	Body
Last modified	13-Apr-2015 00:00:00
Symptom	112000 Latches/Locks & Security

Content

Issue:

Exterior door handle keyless locking sensor does not operate when touched.

Cause:

Quality issue with the exterior door handle sensor.

Action:

Parts currently available have been modified to the latest condition,

If a vehicle is presented with the issue detailed above complete the normal diagnostics using SDD. If the keyless locking sensor is identified as the root cause, replace the door handle assembly

Assured VIN's as follows:-

Range Rover (L405) – LG167709

Evoque (L538) – LV955423

JLR engineering would like to thank everyone who submitted EPQR's highlighting and assisting this investigation. Please only submit further EPQR's for vehicles manufactured after the assured VIN's provided above