

TECHNICAL BULLETIN
LTB00319NAS5
01 SEP 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in gray

SECTION: 501-08

Exterior A-Pillar Molding Loose

AFFECTED VEHICLE RANGE:

LR3 (LA)

Model Year: 2005-2009
VIN: 000360-513325
Manufacturing Plant: Solihull

LR4 (LA)

Model Year: 2010-2013
VIN: 510742-680025
Manufacturing Plant: Solihull

Range Rover Sport (LS)

Model Year: 2005-2013
VIN: 900290-778722
Manufacturing Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The exterior A-pillar molding may become loose.

Cause: This may be caused by the molding's retaining clips losing tension.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

LR077843 A-Pillar Retaining Clips Fitting kit Quantity: 1

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
A-Pillar exterior finisher retaining clips - windshield -	76.43.39	0.1	24	LR053837

Left-hand - Renew				
A-Pillar exterior finisher retaining clips - windshield - Right-hand - Renew	76.43.40	0.1	24	LR053837



NOTE: Normal Warranty procedures apply.

SERVICE INSTRUCTION:



- NOTE: when submitting a claim, state whether the windshield is an original 'Land Rover'- / 'Range Rover'-branded windshield or is a third-party replacement windshield. This will not affect a Warranty claim.**

Install the new A-pillar exterior finisher retaining clips (see TOPIx Workshop Manual, section 501-08).