



# Tech Tips

TT 96-16-01

Date: July 15, 2016

2016 Tiguan – Vehicles equipped with Kessy, Entry Handle electronic indication does not work

The door handle connector may not be fully seated, as a result of connector guide ribs being too long. Trimming the connector ribs will allow the connector to seat fully. See Photos.





# Service Information

---



**WARNING:**

**Be extremely cautious using the blade!**

