

[Next Unread Message](#)**View Message**

**Sent on** 07 06 2015 **Expires on** 07 20 2015  
**From** Parts and Service Division  
**Subject** Request for Visit: 2012-2015 Civic with EPS Light On & DTC 33-01, 33-02, 33-06

**PRIORITY/ACTION REQUIRED**

**To:** All Honda Service Managers/Advisors  
**From:** Technical Research & Support Group  
**Re:** Request for Visit: 2012-2015 Civic with EPS Light On & DTC 33-01, 33-02 and/or 33-06 Stored

**This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this iV message and provide a copy to the Shop Foreman and all Service Advisors.**

**Background**

American Honda (AHM) is investigating certain 2012-2015 Civics with a customer complaint of EPS (Electric Power-Assisted Steering) Light ON with/without loss of power steering assist as well as having the DTC 33-01 (Lower FET Stuck ON), 33-02 (Upper FET Stuck ON) and/or 33-06 (Lower FET Stuck ON) stored. To fully understand the cause of this occurrence, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. VIN must start with 2HG or 19X.
2. At least one of the DTCs (33-01, 33-02, 33-06) must be stored.
3. First time & repeat complaints are accepted.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.