

[Next Unread Message](#)**View Message**

Sent on 06 19 2015 **Expires on** 07 03 2015
From Parts and Service Division
Subject 2016 Pilot Incorrect Wheel Torque Specification - Owner's Manual & PDI Checklist

Message PRIORITY/ACTION REQUIRED

To: All Honda Sales and Service Managers
From: Parts, Service and Technical Division
Re: 2016 Pilot Incorrect Wheel Torque Specification - Owner's Manual & PDI Checklist

Print this iN message and give a copy to all Sales Consultants, Shop Foreman, all Service Consultants, all Technicians, and appropriate personnel.

Dear Sales and Service Managers,

The 2016 Pilot Owner's Manual included on the Owner Information CD and the PDI Checklist book, contain an incorrect wheel torque specification. Service Repair information on SIS for the 2016 Pilot is correct. The correct value is 94 lbf·ft (127 N·m, 13 kgf·m).

American Honda will be mailing a supply of updated CD's and PDI Checklist books to you soon. You will need to use the updated CD and PDI Checklist book to replace the current CD and PDI Checklist book in the glove box kit of any vehicles that you have in inventory, or that you receive until vehicles being produced with the updated CD and PDI Checklist book arrive at your dealership.

Until your supply of CD's and PDI Checklist books arrive, please direct any customers who purchase a 2016 Pilot to owners.honda.com/vehicles/information/2016/Pilot/manuals to view the Owner's Manual. You can also print the attached PDI Checklist book by clicking [Here](#) to download.

Sincerely,
Parts & Service Communications

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.