

View Message

Sent on 06 25 2015 **Expires on** 09 20 2015
From Acura Parts, Service & Technical Division, Campaign Administration
Subject Stop Sale/Safety Recall: 2014-15 MDX A/C Compressor Clutch Bolt

DATE: June 25, 2015

TO: All Acura Sales, Service & Parts Managers and Personnel
FROM: Acura Parts, Service & Technical Division, Campaign Administration

RE: Stop Sale/Safety Recall: 2014-15 MDX A/C Compressor Clutch Bolt

On June 24, 2015 Acura notified NHTSA of a **Stop Sale** order and **Safety Recall** for 2014-2015 model year MDX vehicles. Any new or used vehicles in dealer stock must be repaired per the relevant service bulletin prior to sale. **Refer to the eResponsibility report or VIN Inquiry status to determine which vehicles in your inventory are affected.**

Problem

Due to improper e-coating during component production, the compressor clutch driver bolt may become loose and fall off, or break. As a result, the clutch does not function properly and the A/C blows warm air.

Repair

Affected vehicles require the replacement of the compressor clutch driver bolt with a new bolt.

Parts

Acura is currently procuring repair parts to support this recall. Estimated parts availability is mid-July.

Warranty

Warranty information will be detailed in service bulletin 15-037, *Safety Recall: A/C Compressor Clutch Bolt*.

Service Bulletin

In support of this recall, a placeholder version of service bulletin 15-037, *Safety Recall: A/C Compressor Clutch Bolt* has been posted on Service Information today, June 25, 2015. Once parts are available, the bulletin will be revised to include warranty, parts, and procedure information.

Customer Notification

Acura expects to begin client notifications in late July 2015.

As always, make sure to check the iN VIN status inquiry to determine if a vehicle is eligible for this (or any) open recall.

Click [here](#) for a copy of service bulletin 15-037.

▲ [BACK TO TOP](#)

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.