

---

**2014-15 Accords MIL On with DTC P0335/P0339 Stored**

---

**Background**

American Honda (AHM) is investigating certain 2014 - 2015 Accords with a customer reporting a vehicle with a Malfunction Indicator Light (MIL) on, with DTCs P0335 (CKP Sensor No Signal) and/or P0339 (CKP Sensor Circuit intermittent interruption) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle in a specific condition prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirement:

1. No previous repairs. (CKP Sensor has not been disconnected from engine harness).
2. Repeat complaints OK.
3. No Accord Hybrids.
4. DTC P0335 and/or P0339 must be stored.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you