



INSTRUCTION TO SERVICE

ITS: 5971

SECTION:	600 Customer Options
WRITTEN BY:	K. Baziuk
SUBJECT:	Seal GPS Antenna Connector.

ITS5971

THIS DOCUMENT AND THE CONTENTS DISCUSSED HEREIN ARE THE CONFIDENTIAL AND PROPRIETARY INFORMATION OF NEW FLYER INDUSTRIES CANADA ULC AND NEW FLYER OF AMERICA INC. AND ARE DISCLOSED BY NEW FLYER IN CONFIDENCE. THIS DOCUMENT AND THE CONTENTS HEREIN ARE NOT TO BE DISCLOSED BY THE INTENDED RECIPIENT WITHOUT THE PRIOR WRITTEN AUTHORIZATION OF NEW FLYER. ANY UNAUTHOIZED DISCLOSURE, REPRODUCTION OR OTHER DISTRIBUTION OF THIS DOCUMENT OR INFORMATION IS STRICTLY PROHIBITED AND MAY RESULT IN ACTION BEING TAKEN AGAINST THE PARTY MAKING THE UNAUTHORIZED DISCLOSURE. THIS DOCUMENT AND ALL COPIES HEREOF MUST BE RETURNED TO NEW FLYER UPON REQUEST.

PROCEDURE:

1. Turn the main battery disconnect switch to the "OFF" position.
2. Access the GPS connector located under antenna mounting panel. See Fig. 1.
3. Apply silicone sealant, PN: 5959336 around point where wires penetrate connectors.
4. Apply high adhesive heat shrink, PN: 136366 over connectors and cables.
5. Turn the main battery disconnect switch to the "ON"




Figure 1: Location of GPS Connector.

LABOUR ESTIMATE

	Operation	Men	Hours	Labour Time M X HR
1	Seal GPS Antenna Connector.	1	0.5	0.5

PARTS REQUIRED

Item	Part Number	Description	Qty. per Coach	Units	Notes
1	5959336	SEALER-SILICONE	0.01	EA	
2	136366	TUBE-HEATSHRINK 1.0 SS	0.25	EA	