

NABI: DART Horn Orientation



Prepared by: John Gunter

Approved by: Dan Allen

Property name and Top bus number: DART 304500, 306500, 313000, 314000, 323000

Issue: The horns are failing

Reason/ cause: The horns are holding water

Solution: Orient the horns in a way so that the water can run out

NABI: DART Horn Orientation



Number of buses affected: All DART buses

Estimate repair hours/bus: 15 minutes

Engineering Documentation: N/A

Necessary parts: N/A

Necessary tools: N/A

1. Turn off main battery disconnect switch(es)
2. Locate the horns in front of bud
3. See the orientation of the horns and determine if they need to be re-oriented



Horns oriented in a way that the water cannot run out

4. If the horn is oriented in a way that the water cannot run out then re-orient the horn

NABI: DART Horn Orientation



The horns are being rotated on their current hardware, and will be set just below parallel to ground level.

5. **Check for completeness of work.**
6. **Remove all tools from the work area**
7. **Turn the main battery disconnect switch(es) on.**