

Subject

**Transfer Case Input Shaft Leak**

Market

USA

Service Category

Drivetrain

Section

Transfer/4wd/AwdAwd

Applicability

13-15MY 4runner

**APPLICABLE VEHICLES**

2013-2015

4Runner

**CONDITION**

Certain vehicles may exhibit a leak from the input shaft seal on the transfer case assembly. This leak is typically first identified by fluid collecting at the bottom of the seam between the transmission output and transfer case input mating surfaces. See example photos below:

Mating surface seam



Front of Transfer Case housing



**RECOMMENDATIONS**

- Please create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

**LINK REFERENCES**

This Tech Tip does not contain any link references