



Service Bulletin

PRELIMINARY INFORMATION

Subject: Whistling or Chirping Noise Coming from Front of Engine

Models: 2015 Chevrolet Corvette Z06
Equipped with 6.2L Engine (RPO LT4)

Attention: This PI also applies to any of the above models that may be Export vehicles.

Condition/Concern

Some customers may comment on a whistling or chirp noise coming from the front of the engine during operation.

Recommendation/Instructions

Technicians should replace the positive crankcase ventilation valve (PCV). Refer to Positive Crankcase Ventilation Valve Replacement (LT4) in SI.

Parts Information

Part Number	Description
12646872	VALVE ASM-PCV
12661912	GASKET KIT-INT MANIF

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4068430	Positive Crankcase Ventilation Valve Replacement	2.5 hrs*

*This time is updated from the current Labor Time Guide. The next update of the Labor time Guide will contain this change.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION