



Service Bulletin

PRELIMINARY INFORMATION

Subject: Engineering Information – Water in Tail Lamps

Models: 2015 Chevrolet Camaro

This PI has been revised to end the need for information from the field. Please discard PIE0330.

If you encounter a vehicle with the above concern, refer to published diagnostics in SI.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION